

COUNTY SURVEYOR'S  
T315 R2W OFFICE  
C1/4 • S13  
1977

DATE: 11-10-77

Condition Report On  
Not Found  
 Renewed  
Unrecorded  
Surveyed In  
Referenced Out

Previous Renewal #'s 15A

Monument(s) Found: (Condition and Source) 1 1/2" STEEL  
AUTO AXLE SOLIDLY SET WITH TOP  
FLUSH TO GROUND. CORNER  
IS IN A 3 WAY FENCE CORNER.

Accessories Found: (Condition and Source) A 20" (ORIG 16")  
(RECORD S20E)  
DOUG. FIR STUMP BEARS S 7° E, 13.2'  
HAS ~~#~~ DOUBLE HEALED BLAZES.  
A 22" (ORIG 14") DOUG. FIR BEARS  
(RECORD N20E)  
N 7° E, 7.5' TO CENTER OF TREE.  
(RECORD DISTANCE OF 6.6' IS TO  
FACE) HAS A SINGLE HEALED BLAZE.

#175 ✓

RENEWAL

Monument Set: (Procedure and Description) 2 1/2" BRASS

CAP ON A 1 1/2" GALV. IRON PIPE.

REFERENCING THE AXLE, I REMOVE THE  
AXLE AND PLACE THE BRASS CAP IN

THE EXACT SAME LOCATION. I ~~PLACE~~ <sup>BURY</sup>

THE AXLE ALONGSIDE THE BRASS CAP.

BRASS CAP STAMPED AS SHOWN ON REVERSE.

New Accessories: (Description) A 13" DOUG. FIR

BEARS N68°W, 56.7', SCRIBED "C 1/4

S13 CS BT" ON A DOUBLE BLAZE.

PLACED COUNTY B.T. SIGNS ON THE

ORIGINAL B.T. AND THE NEW B.T.

Location and Comments:

SOME LOCAL  
ATTRACTION  
MAY BE CAUSED  
BY FENCE WIRES.

17°E

U.S.F.S.

DENNIS GAYLORD

" "

ROLAND SIMSHAUSER

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
*[Signature]*