

T245 R6W

S19

C1/4

DATE: NOV. 14, 1977

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

BLM

Monument(s) Found: (Condition and Source) A 2" IRON PIPE WITH
BRASS CAP SET 4" ABOVE GROUND, MARKED "C1/4"
S19
1962

Accessories Found: (Condition and Source) A 12" NOW 17" DIA.

DOUGLAS FIR BEARS N16°E 157³ FT. (REG. 160⁴ FT.) WITH
A SINGLE WELL HEALED BLAZE. A 17" DIA. MAPLE IS
DOWN, (ROTTED OFF AT GROUND), BEARS APPROX. S55°E
48⁸ FT. WITH VISABLE SCRIBING IN PARTLY HEALED
BLAZE.

117 ✓

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 2" +, IN CENTER
CONCRETE
BRIDGE PIER, 6" FROM TOP, BEARS S58°W 164¹ FT.

Location and Comments:
CORNER IS AT BASE
OF HILL, 15 FT WEST
OF FENCE WHICH BEARS
N40°E AND S40°W,
APPROX 5 FT. SOUTH
OF CROSS FENCE,
IN DRAINAGE DITCH.

20°E
DCSO
R.B. KIMBERLING
R.B. Kimberling
P.L. EARLE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK 