

DATE: 12-12-77

T295

R	S25	S30	R
6			5
W	S36	S31	W

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s T29-5
#44, 148 #183 T29-6

Monument(s) Found: (Condition and Source) A 3/4" x 34" GALVANIZED
IRON PIPE, 25" IN THE GROUND. ~~REMOVED~~

Accessories Found: (Condition and Source) A 10" NOW 38" DIA. W. FIR
BEARS S60°W 11³/₄ FT. WITH VISABLE SCRIBING "S31--S IN OPENED
BLAZE (O.B.T.). A 36" NOW 40" DIA. D. FIR BEARS S73 1/4° E 55³/₄ FT.
(REG. 54¹/₂ FT.)
WITH VISABLE BARK SCRIBING "T295 R5W S31CS" AND
CARVED "K" ON N.W. FACE. A 36" NOW 34" DIA. D. FIR BEARS
N67 1/2° W 42³/₄ WITH VISABLE BARK SCRIBING "T295 R6W
S25 CS BT". A 6" NOW 8" W. FIR BEARS N7° E 15³/₄ FT. WITH

#192 T29-5 X
 #244 T29-6 X

C

A WELL HEALED DOUBLE BLAZE, A 9" NOW 14" DIA. W. FIR
BEARS S78 1/2° E (REG. S81° E) 26 1/2 FT. WITH A WELL HEALED
DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) A 1" x 36" IRON PIPE
WITH BRASS CAP SET 5" ABOVE GROUND AND MARKED
"DOUGLAS COUNTY SURVEYOR"
T295 SET 3/4" x 34" IRON PIPE AT
R S25 | S30 R
6 S36 | S31 S
W 1977 W NORTH EDGE OF BRASS CAP,
24" IN THE GROUND.

New Accessories: (Description) NONE

Location and Comments:
CORNER IS SOUTH 12 1/2 FT.
OF AN E-W FENCE,
DUE WEST 64 1/2 FT.
OF A 30" DIA. FIR
STUMP WHICH IS A
FENCE CORNER, FENCE
TO NORTH AND E-W
AND THE
S.W. COR. OF CLEARCUT
UNIT. ~~200R~~

20° E Compass Declination
DCSO Agency
R.B. KIMBERLING Party Chief
R.B. Kimberling Notekeeper
F.C. SILAGY Witnesses

OK
[Signature]