

T295
1/4 COR.
R 524 | 519 R
6 5 W

DATE: 12-13-77

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s ^{163(R5W)} ~~None~~ (SEE M37-20) #205 T29-6

Monument(s) Found: (Condition and Source) A 1" X 36" IRON PIPE

WITH BRASS CAP SET 14" ABOVE GROUND AND MARKED
"COUNTY SURVEYORS OFFICE"

T295
R 524 | 519 R
6 5 W
1/4
1969

CORNER WAS PROPORTIONED

BETWEEN THE N.W. COR. 519

AND S.W. COR. S30, NEEDS

RESURVEYED SINCE THE S.W.

COR. 519 HAS BEEN FOUND.

I MOVE CORNER S74°21'34"W

885 FT.

Accessories Found: (Condition and Source) A 10" DIA. D. FIR BEARS

N68 1/2° W 14 1/2 FT. (REG. S 87° W 21 3/4 FT.) WITH A WELL HEALED

DOUBLE BLAZE. A 7" DIA. W. OAK BEARS N86° E 23 1/2 FT.

(REG. N 82° E 16 1/2 FT.) WITH VISABLE SCRIBING "S19"

IN PARTLY HEALED DOUBLE BLAZE.

#241 T29-6 ✓
#189 T29-5 ✓

Page 1 of 1
G. S. File No. 59/42-30

C

RENEWAL

Monument Set: (Procedure and Description) I RESET BRASS

CAP AS DESCRIBED. CAP IS 6" ABOVE GROUND IN A
18" DIA. MOUND OF STONE AND MARKED "RESET 1977".

I SET A 1"x30" IRON ROD IN ORIGINAL B.C. LOCATION,

WITH A 1 1/2" DIA. ALUM. CAP SET 6" ABOVE GROUND IN A
18" DIA. MOUND OF STONE AND MARKED "DOUGLAS CO."
1977

New Accessories: (Description) NONE SURVEYOR

Location and Comments:

N.-S. FENCE BEARS
EAST 20³ FT.

BOOMER HILL RD.
BEARS NORTH 124 FT.

20°E

DCSO

R. B. KIMBERLING

R. B. Kimberling

E. C. SILAGY

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK 