

T295
 R S R
 6 5/16 5
 W 524/S19 W

DATE: 12-13-77

Condition Report On
 Not Found
 Renewed
 Unrecorded
 X Surveyed In
 Referenced Out

Previous Renewal #'s NONE (SEE M37-20)

Monument(s) Found: (Condition and Source) A 1" x 36" IRON PIPE WITH BRASS CAP SET 16" ABOVE GROUND AND MARKED "COUNTY SURVEYORS OFFICE"

T295 CORNER WAS SET BY PROPORTION
 R S R
 6 1/16 5 BETWEEN THE N.W. COR. S19 AND
 W 524/S19 W S.W. COR. S 30, NEED FOR RESURVEY
 1969 SINCE THE S.W. COR. S19 HAS BEEN
 FOUND. I MOVE CORNER S70°04'W
 12 9/16 FT.

Accessories Found: (Condition and Source) A 17" NOW 18" DIA. D. FIR BEARS N73°E 35 1/2 FT. (REC. N73°E 25 1/2 FT) WITH A WELL HEALED DOUBLE BLAZE. A 9" NOW 12" DIA. D. FIR BEARS S0 1/2°E 19 1/2 FT. (REC. S27°W 27° FT.) WITH A WELL HEALED DOUBLE BLAZE.

#242 T29-6 X
 #196 T29-5 X

Page 1 of 1
 C. S. File No. 59/42-31 C

RENEWAL

Monument Set: (Procedure and Description) I RESET BRASS

CAP AS DESCRIBED. CAP IS 5" ABOVE GROUND AND
MARKED "RESET 1977" ABOVE "1969". I SET A 1"x30"
IRON ROD IN ORIGINAL CAP LOCATION, ~~S~~ WITH A 1/2" DIA.
ALUMINUM CAP SET 4" ABOVE GROUND AND MARKED

"DOUGLAS CO."
1977
SURVEYOR

New Accessories: (Description) NONE

Location and Comments:

A N-S FENCE BEARS
EAST 39 1/2 FT.

20°E Compass Declination
DCSO Agency
R.B. KIMBERLING Party Chief
R.B. Kimberling Notekeeper
E.C. SILAGY Witnesses

