

T295  
R 513 | 518 R  
6 524 | 519 S  
W  
1977

DATE: 12-14-77

Condition Report On  
Not Found  
 Renewed  
Unrecorded  
Surveyed In  
Referenced Out

#157 T29-6

Previous Renewal #'s #132 (R5W) - SEE M37-20

Monument(s) Found: (Condition and Source) A 1" x 27" IRON PIPE

Accessories Found: (Condition and Source) A 12" NOW 44" DIA. B.  
OAK BEARS S85°W 46<sup>1</sup> FT. (REG. 56<sup>1</sup> FT.) WITH A CHOPPED OPEN  
BLAZE, 12" DIA. CENTER ROTTED AWAY AND ANOTHER WELL  
HEALED ~~BY~~ DOUBLE BLAZE <sup>AT</sup> THE LEFT SIDE OF CHOPPING.  
A 40" DIA. B. OAK BEARS N0<sup>1</sup>/<sub>2</sub>°E 72<sup>8</sup> FT. WITH SCRIBE  
MARKS VISABLE IN AN ALMOST HEALED DOUBLE BLAZE.  
A 48" DIA. B. OAK BEARS N82°W 75° FT. WITH A WELL HEALED

#187 T29-5

#239 T29-6

Page 1 of 1  
U. S. File No. 59/42-32

C

BLAZE, A ~~1 1/2~~ 24" DIA. <sup>W.</sup> OAK BEARS S15°E 134 ± FT. WITH  
 A WELL HEALED BLAZE.

RENEWAL

Monument Set: (Procedure and Description) A 1" x 36" IRON PIPE  
WITH BRASS CAP SET 6" ABOVE GROUND MARKED  
"DOUGLAS COUNTY SURVEYOR"  
I SET THE IRON PIPE AT THE  
N. EDGE OF THE BRASS CAP.

T 295  
 R S 13 | 518 R  
 6 W S 24 | 519 W  
 1977

New Accessories: (Description) NONE

Location and Comments: \_\_\_\_\_ 20°E Compass Declination  
CORNER IS AT S.W. \_\_\_\_\_ DCSO Agency  
EDGE OF A 7 FT. \_\_\_\_\_ R.B. KIMBERLING Party Chief  
HIGH FENCE POST, \_\_\_\_\_ R.B. Kimberling Notekeeper  
~~POST~~ 8 FT, N.W. E.C. SILAGY \_\_\_\_\_  
OF A FENCE CORNER \_\_\_\_\_  
TO THE WEST AND \_\_\_\_\_  
N.-S. \_\_\_\_\_

Witnesses  
 OK *[Signature]*