

DATE: 3-23-78

T 275  
R 7 W    1 | 6    R 6 W  
          1/4

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #137 T27-7 #9727-6

Monument(s) Found: (Condition and Source) A 1 1/4" IRON PIPE, BENT  
OVER, 3" ABOVE GROUND BEARS S58°E 1 1/2 FT. WITH A 1" X 26"  
HOLLOW DRILL ROD AT THE SOUTH EDGE, SET 6" BELOW GROUND.

Accessories Found: (Condition and Source) (O.B.T.) A 13" NOW 42" DIA.  
W. OAK BEARS S52 3/4° W 23 1/2 WITH A WELL HEALED BLAZE.  
(REN #137) A 10" NOW 26" DIA. W. OAK BEARS S65°E 44 1/2 FT. (REC.  
S67 1/2°E 43 1/2 FT) WITH A WELL HEALED DOUBLE BLAZE  
(LOWER PART OF UPPER BLAZE IS ROTTED)

#189 T27-7 ✓  
#153 T27-6 ✓

RENEWAL

Monument Set: (Procedure and Description) SET A 1"x36" IRON PIPE  
WITH A BRASS CAP SET 4" ABOVE GROUND, MARKED  
"DOUGLAS COUNTY SURVEYOR"  
T275

R  
7 51 | 56 R  
W W  
1/4

New Accessories: (Description) NONE

Location and Comments: \_\_\_\_\_ 20°E \_\_\_\_\_ Compass Declination  
CORNER IS 40 FT. SOUTH \_\_\_\_\_ DCSO \_\_\_\_\_ Agency  
OF ORCHARD LANE, 1 FT. R.B. KIMBERLING \_\_\_\_\_ Party Chief  
NORTH OF AN EAST-WEST R.B. Kimberling \_\_\_\_\_ Notekeeper  
FENCE, 16 FT WEST OF P.L. EABLE \_\_\_\_\_ Witnesses  
A FENCE TO THE SOUTH. \_\_\_\_\_  
\_\_\_\_\_ OK [Signature]