

COUNTY SURVEYOR'S
T265 R1W
1/4 S27 T52G
OFFICE
1978

DATE: 1-19-78

- Condition Report On
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) NONE

FALLS IN SKIP TRAIL

Accessories Found: (Condition and Source) A 36" DOUG

FIR STUMP WITH PARTLY HEALED
BLAZE BEARS N47°E, 6.6' SCRIBING
VISIBLE "4 S26" STUMP HAS BEEN
SLIGHTLY DISTURBED DURING LOGGING.
BT TO NW IS GONE.

#83X

RENEWAL

Monument Set: (Procedure and Description) 2 1/2" BRASS
CAP ON 1" IRON PIPE STAMPED AS
SHOWN ON REVERSE, USED ONLY
REMAINING BT STUMP AS
REFERENCE,

New Accessories: (Description) A 34" DOUG. FIR
BEARS S 69 1/2° E, 211.0' SCRIBED
"1/4 S 26 CS BT" ON A DOUBLE
BLAZE, I SET A 5/8" RE-BAR IN A
36" FIR STUMP, RE-BAR BEARS
S 34° W, 28.9' PLACE CO. BT, SIGNS
ON ALL 3.

Location and Comments:

20° E

Compass Declination

USFS

Agency

D. GAYLORD

Party Chief

" " "

Notekeeper

ROLAND SIMSHOUSE

Witnesses

OK
[Signature]