

DATE: 4-13-78

T305
R 6 536 | 530 R
W | 531 W

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s #62, #223 T30-5 #144 T30-6

Monument(s) Found: (Condition and Source) A 1" x ~~32~~ 44" IRON PIPE SET 32" IN THE GROUND.

Accessories Found: (Condition and Source) OBT'S ^{DIA.} A 15" NOW 42" REMAINS OF STUMP AT GROUND LEVEL BEARS N44 1/2° E ^{62 1/2} ~~64~~ FT. (REC. N42° E 64° FT.). A STUMP HOLE BEARS APPROXIMATELY S80° E 55° FT. (REC. 56 1/2 FT.). A 6" NOW 18" DIA. B. OAK IS DOWN, ~~55~~ ORIGINAL POSITION APPROX. BEARS N7° W 31° FT., ~~A~~ 1 CHOP OPEN WELL HEALED BLAZE TO FIND SCRIBING HAS BEEN CHOPPED OUT. A 5" NOW 15" DIA. B. OAK BEARS S88° W @ 42° @ 22° = 39 1/2 FT. (REC. S85° W 40 3/4 FT.) WITH A

#275 T30-5 ✓
#223 T30-6 ✓

BADLY ROTTED BLAZE, APPARENTLY CHOPPED OUT.
REN #62
A 10" NOW 20" DIA. FIR STUMP, 5 FT. HIGH, BEARS N. 31° E (REC.
N 29° E) 61 1/2 FT. WITH VISABLE SCRIBING "S30CC" IN A PARTLY

HEALED DOUBLE BLAZE. A 16" NOW 18" DIA. FIR STUMP BEARS
S 72° 22' E 13 1/2 FT. WITH A ROTTED OUT BLAZE. REN #223 A 16" NOW 18" DIA.
D. FIR BEARS S 31 1/2° E (REC 56° E) 24 3/4 FT. WITH A DOUBLE WELL HEALED BLAZE.

RENEWAL

Monument Set: (Procedure and Description) A 1" x 3/4" IRON PIPE WITH
A BRASS CAP SET AT GROUND LEVEL AND MARKED

"DOUGLAS COUNTY SURVEYOR"
T305
I SET 1" x 44" IRON PIPE AT NORTH
EDGE OF B.C., 32" IN THE GROUND.

R	S36	S30	R
6			S
W		S31	W
1978			

New Accessories: (Description) A 6" DIA. D. FIR BEARS N 41° E 20 1/2 FT.
I DOUBLE BLAZE AND SCRIBE "T305 R5W S30CS BT". A 7" DIA. D. FIR
BEARS S 16° E 6 1/2 FT., I DOUBLE BLAZE AND SCRIBE "T305 R5W S31CS BT".

Location and Comments: _____ 20° E _____ Compass Declination
 CORNER IS 6 FT. EAST OF _____ DCSO _____ Agency
 A N-S WIRE FENCE, 125 FT _____ R.B. KIMBERLING _____ Party Chief
 EAST OF A DIRT ROAD WEST _____ R.B. Kimberling _____ Notekeeper
 OF SMALL CREEK. _____ F.C. SILAGY _____ Witnesses

_____ P.L. EARLE _____
 _____ OK _____