

TZ15 R11W

DATE: 3-8-78

59 | 510
516 | 515

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #8

Monument(s) Found: (Condition and Source) FOUND A 3/4" DIA. IRON PIPE
6" ABOVE GROUND
(NO RECORD) NEXT TO TWO SQUARED WOODEN POSTS.

(O.B.T.)

Accessories Found: (Condition and Source) A 36" DIA. NOW 78" DIA.

CEDAR BEARS N60°W 49⁵ FT. WITH A CHOPPED OPEN BLAZE
AND ROTTED OUT CENTER. -

(REN. #8)

A 48" NOW 57" FIR STUMP BEARS N23°E 51⁸ FT. (REC.

50⁸ FT. GOOD TO ORIG. FACE) WITH A DOUBLE WELL

HEALED BLAZE. A 60" DIA. CEDAR STUMP BEARS N67°W 70⁶ FT.
BADLY ROTTED.

#106 X

RENEWAL

Monument Set: (Procedure and Description) A 1"x36" IRON PIPE OVER
3/4" IRON PIPE
(DRIVEN 2° FT. BELOW GROUND), WITH A BRASS CAP SET 6" ABOVE
GROUND AND MARKED "DOUGLAS COUNTY SURVEYOR"
T215 R11W
59 | 510
I SET SQUARED WOODEN POSTS 516 515
1978
UP AND DOWNHILL ON A STEEP NW SLOPE.

New Accessories: (Description) A 18" DIA. MAPLE BEARS 577° E
78^{1/2} FT. DOUBLE BLAZE AND MARK "T215 R11W 515 CS BT". A 12" DIA.
LEANING MAPLE BEARS 515° W 51° FT. DOUBLE BLAZE AND MARK
"T215 R11W 516 CS BT". A 19" DIA. LEANING I. CEDAR BEARS
N21 1/2° W 41° FT @ -31° = 35 1/2 FT. (MEAS. TO CENTER AT GROUND), DOUBLE
BLAZE AND MARK "T215 R11W 59 CS BT". A 20" DIA. I. CEDAR BEARS
N19 1/2° E 40° FT. @ -11° = 39 1/2 FT. DOUBLE BLAZE AND MARK "T215
R11W 510 CS BT".

Location and Comments:
CORNER IS 0.6 MI. EAST
OF ABBOTT HOUSE UP
PRIVATE RD., THEN
300 FT. SOUTH UP CANYON
AND 100 FT. UP A NW
SLOPE.

20° E Compass Declination
DC30 Agency
R. B. KIMBERLING Party Chief
R. B. Kimberling Notekeeper
P. L. EARLE Witnesses
OK [Signature]