

T295

DATE: 1-4-78

$\frac{1}{4}$ S21 $\frac{1}{2}$ S22
R6W

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #45, #47, #214

Monument(s) Found: (Condition and Source) A 1" IRON PIPE WITH BRASS
CAP SET 14" ABOVE GROUND AND MARKED "COUNTY SURVEYORS OFFICE"

T295
 $\frac{1}{4}$ S21 $\frac{1}{2}$ S22
R6W
1971

A 6"x6" CEDAR POST IS LAYING ALONGSIDE B.C. WITH
VISABLE SCRIBING "SCS" ON ONE FACE.

Accessories Found: (Condition and Source) A 14" NOW 15" DIA. FIR
BEARS N76°E 9^B FT. (REC. N73°E 9^E FT.) WITH A WELL HEALED
DOUBLE BLAZE. A 15" NOW 24" DIA. FIR STUMP IS PARTLY
UPROOTED, ORIGINAL POSITION APPROX. S62°W 34° FT
WITH VISABLE REVERSE SCRIBING "S21CS" LOOKING
BACK FROM ROTTED CENTER OF STUMP.

#295 4

G.S. File No. 59/46-59

Page 1 of 1
C

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 18" DIA. D. FIR BEARS

16 ± FT.

S33°W WITH SCRIBED "1/4 S 21 CS BT" IN DOUBLE BLAZE.

Location and Comments:

CORNER IS 35 FT.
NORTH OF BLM
ROAD

20°E

Compass Declination

DCSO

Agency

R. B. KIMBERLING

Party Chief

R. B. Kimberling

Notekeeper

F. C. SILAGY

Witnesses

OK
[Signature]