

T295 RBW

DATE: 3-20-78

9 / 10
1/4

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 27, 133

Monument(s) Found: (Condition and Source) AT THE CORNER POINT, WE FIND
A 1/2" IRON ROD (REN. #27 REC. 3/4" I ROD) AND A 1" ~~3/4~~ I. PIPE, EXTENDING
12" ABOVE GROUND, WITH BRASS CAP ATTACHED, MARKED:

COUNTY SURVEYOR'S OFFICE

T295 RBW

1/4 59 | 510

1967

Accessories Found: (Condition and Source) AN ORIGINAL BT, A 20" NOW
40" FIR, DOWN AND ROTTEN, WITH SCRIBING "1/4 59 BT" VISIBLE ON UNHEALED
BLAZE BEARS N 1/2° E 57⁺ FT., AND AN ORIGINAL BT, A 50" NOW 60"
D. FIR, DOWN, NO MARKS VISIBLE, BEARS N 1/2° W 35[±] FT.

FROM REN. # 27, A 30" NOW 36" HEMLOCK, ALIVE WITH WELL-HEALED
 DOUBLE BLAZE BEARS N 70 1/2° W 55[±] FT., AND A 48" D. FIR, WITH BARK
 SCRIBING "1/4 510 CS BT" VISIBLE ON DOUBLE BLAZE BEARS S 44° E

#1754

G. S. File No. 59/46-60

Page 1 of 1

C

39 ¹/₄ FT. (REG. S 46° E BEARING, 37 ⁵/₈ FT. DISTANCE IS GOOD TO FACE)

FROM REN. # 133, A 15" NOW 18" R. CEDAR, WITH SCRIBING

"451C" VISIBLE ON PARTIALLY-HEALED DOUBLE BLAZE, BEARS

S 37° E 11 ¹/₄ FT.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) WE MARK THE FOLLOWING

NEW BT: A 12 " I. CEDAR SCRIBED " ¹/₄ S 10 CS BT " ON A
DOUBLE BLAZE, BEARS N 55° E 143 ¹/₂ FT.

Location and Comments:

20° EAST

NOTE: THE FIR AND CEDAR BT'S IN THE SE QUADRANT WILL BE CUT IN THE NEAR FUTURE DURING CLEARING FOR A NEW POWER LINE.

DOUGLAS CO. SURVEYOR'S OFFICE

GARY LANGLITZ

Gary L. Langlitz

FRANK C. JILAGY

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]