

T295 RBW

DATE: 3-1-78

59	510
516	515

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #72

Monument(s) Found: (Condition and Source) A 1" IRON PIPE WITH

BRASS CAP SET 4" ABOVE GROUND AND MARKED

"COUNTY SURVEYOR'S

T295 RBW

59	510
516	515

OFFICE 1958

(OBT'S)

Accessories Found: (Condition and Source) A 40" N.W. 50" DIA. FIR

BEARS N10°E 24 $\frac{1}{2}$ FT. (REC. 22 $\frac{1}{2}$ FT. GOOD TO ORIGINAL FACE),

WITH VISABLE BARK SCRIBING "S T295 RBW S". A 40" N.W. 60"

DIA. FIR, UPROOTED, WITH CENTER OF ROOT HOLE BEARING

APPROX.

S55°E 50 FT (REC. 3 $\frac{3}{4}$ FT. GOOD TO ORIGINAL FACE), WITH

VISABLE BARK SCRIBING "T2 T295 RBW S15".

(REN #72) A 12" N.W. 17" DIA. D. FIR BEARS N41°W 141 $\frac{1}{2}$ FT. WITH

#177 x

Page 1 of 1

G. S. File No. 59/46-61

C

A WELL HEALED DOUBLE BLAZE. A 5" NOW 12" DIA. CEDAR
BEARS N46°E 80 FT. WITH A WELL HEALED BLAZE 5 FT. ABOVE
GROUND. A 3" NOW 10" DIA. D. FIR BEARS ~~S58°W~~
559°W 412 FT. (REG.
S58°W) WITH A WELL HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 6" DIA. D. FIR BEARS N82°E
118⁵ FT., DOUBLE BLAZED AND MARKED "T295 RBW S10CS BT".
A 7" DIA. D. FIR BEARS S13°E 340 FT., DOUBLE BLAZED AND
MARKED "T295 RBW S15CS BT".

Location and Comments: _____ 20°E Compass Declination
CORNER IS IN ROOT _____ DCSO Agency
HOLE OF 60" DIA. O.B.T. RB KIMBERLING Party Chief
RB Kimberling Notekeeper
P.L. EARLE Witnesses

OK
[Signature]