

2-18-75

T 22S R 12W

RENEWAL NO. 4

5 x 4

FD. OK.

CORNER LIES APPROX 40 FEET WEST OF SHOULDER OF NEWLY CONSTRUCTED ROAD

SEE CS FILES OF FORD SURVEY, POSSIBLY GET COPY OF TIE FROM 1/4 CORNER TO S.H. ROAD

RENEWAL NO. 105

DIETZEN NO. 385-6

R 13W R 12W

T 22S

25 x 30

CORNER FOUND AS DESCRIBED. IRON PIPE NOW BADLY RUSTED.

C.S. 59/46-68