

T30S R5W

DATE: 5-1-78

S.W. COR.  
ROBERTS  
D.L.C. 59

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #33

Monument(s) Found: (Condition and Source) A 1" IRON PIPE, 6" ABOVE  
GROUND (NO RECORD FOUND).

Accessories Found: (Condition and Source) (O.B.T.)  
A REMAINS OF AN OAK,  
SIZE INDETERMINATE, BEARS N10°E 46<sup>±</sup> FT. WITH REMAINS OF A  
BLAZE BUT NO SCRIBE MARKS. (REN. #33) A 18" NOW 20" DIA. FIR STUMP,  
BADLY ROTTED, BEARS N32°W 76<sup>±</sup> FT.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

~~CORNER IS~~  
1" I.P. IS ON A N-S  
SPUR RIDGE

	<u>20°E</u>	Compass Declination
	<u>DCSO</u>	Agency
<u>L.E. MONBEAN</u>		Party Chief
<u>R.B. Kimberling</u>		Notekeeper
<u>P.L. EARLE</u>		Witnesses
<u>S.J. FLAUSE</u>		

OK *[Signature]*