

T 32 S R 2 W

DATE: 5-2-78

MOUNTAIN TOP #2
CORNER #2

MINERAL SURVEY # 792

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL

CEDAR CORNER POST.

Accessories Found: (Condition and Source) FROM THE 1916 MINERAL

SURVEY, WE FIND THE FOLLOWING BEARING TREE:

AN ORIG. 18" NOW 34" D. FIR ALIVE WITH WELL-HEALED SINGLE

BLAZE BEARS S 56° W 43° FT. (Rec. S 55° 53' W 43° FT.)

THE ORIGINAL NE BEARING TREE, A 7" LABEL IS GONE.

#108 X

C

RENEWAL

Monument Set: (Procedure and Description) AT A POINT WHICH AGREES
WITH THE RECORD MEASUREMENTS TO THE ONLY REMAINING ORIGINAL
BEARING TREE PREVIOUSLY DESCRIBED, WE SET A 1" X 30" IRON PIPE, 27
INCHES IN THE GROUND, WITH BRASS CAP ATTACHED, MARKED:

DOUGLAS CO SURVEYOR

T 325

New Accessories: (Description) MT 2-2 / MS
792

WE MARK NEW BEARING TREES AS R2W
1978

FOLLOWS:

AN 18" D. FIR SCRIBED "MT 2-2 MS 792 CS BT" ON A DOUBLE BLAZE
BEARS S 25° E 10^B FT..

AND A 10" D. FIR SCRIBED "MT 2-2 MS 792 CS BT" ON A DOUBLE
BLAZE BEARS N 66 1/2° W 21^B FT..

Location and Comments: 20° EAST Compass Declination

DOUGLAS CO. SURVEYOR'S OFFICE Agency
GARY L. LANGLITZ Party Chief
Gary L. Langlitz Notekeeper
FRANK C. JILAGY Witnesses

OK
[Signature]