

COUNTY SURVEYOR'S OFFICE  
R 1 W T 245  
S 13 1/4 S 18 E  
1978

DATE: 5-4-78

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) <sup>AFTER</sup> A THOROUGH

SEARCH, DID NOT ~~SEE~~ FIND THE ORIGINAL CORNER STONE.

Accessories Found: (Condition and Source) ORIGINAL 36"

FIR IS NOW A 31" SNAG 20' HIGH.

BEARS N 25° E, 31.02' OPEN & FIND SCRIBING "1/4 S BT" THE ORIGINAL

60" FIR HAS FALLEN & SLIP DOWNHILL APPROX. 100' NO SCAR VISIBLE. STUMP

HOLE BEARS S 52° W, 64.68'

#129-724-1W X

U.S. File No. 60/111-6

Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) USING THE ORIG

B.T. SNAG FOR REFERENCE, I SET A

2 1/2" BRASS CAP ON A 1" IRON PIPE

AT CORNER POINT. BRASS CAP STAMPED

AS SHOWN ON REVERSE.

New Accessories: (Description) A 18" DOUG. FIR

BEARS N34°E, 35.0' SCRIBED "1/4 S18 CSBT"

ON A DOUBLE BLAZE.

A 12" DOUG. FIR BEARS N 11°30'W, 16.2'

SCRIBED "1/4 S13 CSBT" ON A DOUBLE BLAZE.

PLACED COUNTY B.T. SIGNS ON TWO NEW B.T.S  
& ON ORIG. B.T. SNAG.

Location and Comments:

CORNER FALLS ON  
A 75% SOUTH

SLOPE.

20°E

V.S.I.S.I.

DENNIS GAYLORD

" "

ROLAND SIMSHAUSER

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
