

COUNTY SURVEYOR'S  
T26S R3E  
1/4 513  
524  
1978  
OFFICE

DATE: 5-11-78

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) NONE

ORIGINAL BRASS CAP SET IN 1930  
HAS BEEN DESTROYED BY LOGGING  
OPERATIONS

Accessories Found: (Condition and Source) ORIGINAL 30"

NOW 34" DOUG FIR STUMP BEARS N48°E,  
58.08'. OPEN & FIND SCRIBING & REVERSE  
"BT". ORIGINAL PINE B. T. TO THE  
S.W. HAS BEEN DESTROYED BY ROAD  
CONSTRUCTION.

# 4 ✓

RENEWAL

Monument Set: (Procedure and Description) USING THE ORIGINAL FIR B.T. STUMP AS REFERENCE,  
I ~~SET~~ SET A 2 1/2" BRASS CAP ON A 1" IRON PIPE. BRASS CAP IS STAMPED AS SHOWN ON REVERSE.

New Accessories: (Description) A 25" DOUG FIR BEARS N 14° E, 80.1' SCRIBED "1/4 S 13 CS BT" ON A DOUBLE BLAZE. A 9" RED FIR BEARS S 35° 30' W, 108.3' SCRIBED "1/4 S 24 CS BT" ON A DOUBLE BLAZE. THIS B.T. IS ACROSS ROAD # 2687. (ON SOUTH SIDE OF RD.)  
PLACED B.T. SIGNS ON BOTH.

Location and Comments: 20° E Compass Declination  
CORNER IS 30' N. S. F.S. Agency  
NORTH OF F.S. DENNIS GAYLORD Party Chief  
ROAD # 2678 " " Notekeeper  
RANDAL LOPEZ Witnesses

OK  
