

T225 RTW

S 1/16

526 | 525

DATE: 5-15-78

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s NONE - SEE M1-59

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) A 18" NOW 20" DIA. D. FIR  
IS UPROOTED, ORIGINAL POSITION APPROXIMATELY BEARS N49 1/2° E  
31 E, WITH A WELL HEALED SINGLE BLAZE. A 14" NOW 20" DIA.  
D. FIR BEARS N39° W 20 1/4 FT. WITH A SINGLE WELL HEALED  
BLAZE

#177 X

C. S. File No. 60/11-8

Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) A 1"x36" IRON PIPE  
WITH A BRASS CAP SET AT GROUND LEVEL IN A TERRACED  
AREA AND MARKED "DOUGLAS COUNTY SURVEYOR"

T223 R7W

S 1/16

S26 | S25

1978

New Accessories: (Description) A 13" DIA. D. FIR BEARS N77 1/2° E  
24 3/4 FT., I DOUBLE BLAZE AND SCRIBE "S 1/16 S25 CS BT",

Location and Comments:

CORNER IS ON A  
40° S.E. SLOPE,  
50 FT. NORTH OF  
A SMALL STREAM

20° E

Compass Declination

DC50

Agency

R. B. KIMBERLING

Party Chief

~~R. B. Kimberling~~

Notekeeper

~~S. F. C. SILAGY~~

Witnesses

OK  
JH