

U. S. GENERAL LAND OFFICE SURVEY

DATE: 6-16-78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1/4  $\frac{526}{535}$

1923

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) 2 1/2" BRASS  
CAP ON A 3/4" IRON ROD. BRASS  
CAP STAMPED AS SHOWN ABOVE.  
MONUMENT HAS BEEN REMOVED FROM  
GROUND BY LOGGING ACTIVITIES & IS  
LYING AT APPROXIMATE CORNER  
LOCATION.

Accessories Found: (Condition and Source) ORIGINAL 10", NOW  
15" HEMLOCK BEARS S82°W, 17.82' HAS  
A HEALED SCAR. ORIGINAL 14", NOW A  
18" DOUG. FIR BEARS N39°30'W, 19.8'  
HAS A HEALED SCAR. PLACED COUNTY  
B.T. SIGNS ON BOTH B.T.'S

#104 X

G. S. File No 60/11-17

RENEWAL

Monument Set: (Procedure and Description) USING THE  
ORIGINAL B.T.'S FOR REFERENCE, I RE  
SET THE G.L.O. BRASS CAP &  
BUILD A MOUND OF STONE AROUND PIPE.  
I ADD "T285 R2W" TO BRASS CAP.

New Accessories: (Description) NONE

Location and Comments: 18° 30' E Compass Declination  
U.S. F.S. Agency  
DENNIS GAYLORD Party Chief  
" " Notekeeper  
JUAN ORTEGON Witnesses

OK  
[Signature]