

U.S. GENERAL LAND OFFICE SURVEY
1929
1/4 520
529

DATE: 6-19-78

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2 1/2" BRASS CAP
ON A 3/4" IRON ROD. ROD IS SET
FIRMLY IN GROUND, BUT BADLY BENT.
BRASS CAP STAMPED AS SHOWN ABOVE.

Accessories Found: (Condition and Source) ORIGINAL 12",
NOW 20" HEMLOCK BEARS N 1° W, 22.8'
(RECORD DISTANCE IS 23.1') HAS A
HEALED SCAR. ORIGINAL B.T. TO THE
SE IS GONE.

#3 ✓

C

RENEWAL

Monument Set: (Procedure and Description) REFERENCING
THE LOCATION OF THE ROD, I REMOVE,
STRAIGHTEN & RE-SET THE ORIGINAL
MONUMENT & BUILD A ROCK MOUND AROUND
PIPE, I ADD "T275 R3E" TO BRASS
CAP.

New Accessories: (Description) A 19" WHITE FIR BEARS
S 29° W, 41.2' SCRIBED "1/4 S 29 CS BT"
ON A DOUBLE BLAZE.

Location and Comments:

18° E Compass Declination
D. S. F. S. Agency
DENNIS GAYLORD Party Chief
" " Notekeeper
BERNARDINO MORALES Witnesses

OK 