

DATE: 6-29-78

T295 R6W

1/4

534 | 535

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s #122, Vol. 30 Pg. 12, B42, #248

Monument(s) Found: (Condition and Source) A 5/8" x 30" IRON ROD WITH

ALUMINUM CAP SET 10 FT. ABOVE GROUND AND MARKED "T295 R6W".

34 | 35

1/45

LS498 1978

(REN. 122)

Accessories Found: (Condition and Source) AT LOCATION OF IMPROPERLY

SET 1/4 CORNER A 5/8" IRON ROD BEARS N 6 1/2° W 30 FT. I ATTACH

AN ALUMINUM CAP MARKED "DOUGLAS CO. SURVEYOR". A 18" DIA.

1978

FIR STUMP NOW BEARS N 22° E 56 1/2 FT. (REC. N 48 1/2° E 33° FT.), WITH SCRIBING "BT" IN BOTTOM BLAZE.

A 12" NOW 16" DIA. FIR IS UPROOTED, ROOT HOLE BEARS N 45° W 41 FT.

(REC. N 84 3/4° W 27° FT.) A 40" DIA. FIR SNAG, 70 FT. HIGH BEARS

WITH SCRIBING "T295 R6W 1/4 534 CS BT" IN A PARTLY HEALED DOUBLE BLAZE.

Page 1 of 1

#253 X

C.S. File No. 60/11-25

N 84°E 23² FT. (REC 545³/₄°E 39⁶ FT.)

RENEWAL

Monument Set: (Procedure and Description) A 1" x 36" IRON PIPE WITH
BRASS CAP SET 4" ABOVE GROUND, MARKED "DOUGLAS COUNTY SURVEYOR"
I SET ALUM CAP UNDER NORTH EDGE OF B.C.

T29S R6W

V4

S34 | S35

1978

New Accessories: (Description) NONE

Location and Comments:

CORNER IS APPROX.

40 FT. EAST OF FENCE.

20°E

DC50

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

D. B. KIMBERLING

R. B. Kimberling

S. J. FLAUSE

OK
[Signature]