

SURVEYOR'S
T305 R2W
OFFICE
COUNTY
1/4 S12

DATE: 8-30-78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

(SOUTH 1/4 SEC. 12 ONLY)

1978

Previous Renewal #'s 53

Monument(s) Found: (Condition and Source) 1" O.D. x 34"

IRON PIPE SET SOLIDLY IN GROUND.

Accessories Found: (Condition and Source) ORIGINAL B.T.

TO THE NE IS BLOWN DOWN, STUMP
HOLE BEARS N 40° E, 5.9 FT. MARKHAM'S

B.T.'S, A 14" CEDAR BEARS S 21° W, 36.1 FT

SCRIBING VISIBLE, "BT 1/4 S12" ON A SINGLE BLAZE

A 20" CEDAR BEARS N 47° W, 40.4 FT.

SCRIBED "1/4 S12 BT" ON A DOUBLE BLAZE.

#216X

BRASS CAP FOR S 13 ONLY (WHICH I
RENEWED THIS A.M.) BEARS N 89° 45' W,
57.5 FT.

RENEWAL

Monument Set: (Procedure and Description) REFERENCING
THE IRON PIPE, I MOVE IT ASIDE AND SET
IN IT'S PLACE A 1 1/2" IRON PIPE WITH A
2 1/2" BRASS CAP, STAMPED AS SHOWN ON
REVERSE, ATTACHED. I BURY THE 1" IRON
PIPE ALONGSIDE THE BRASS CAP.

New Accessories: (Description) _____
NONE

I PLACED COUNTY B.T. SIGNS ON BOTH B.Ts

Location and Comments: 5° E (SEE COMMENT) Compass Declination
LOCAL ATTRACTION U. S. F. S. Agency
CAUSED BY A DENNIS GAYLORD Party Chief
METAL FENCE " " Notekeeper
POST SETTINGS 1.2 FT JAMES DAVIS Witnesses
EAST OF THE _____
BRASS CAP. _____