

T295 R8W

DATE: 10-2-78

$\frac{1}{4} \frac{1}{12}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 126

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL CORNER
POST. FOUND AT THE CORNER POINT, A 1" IRON PIPE, FIRMLY SET, EXTENDING 8 INCHES
ABOVE GROUND ON A STEEP NE SLOPE, WITH BRASS CAP ATTACHED, MARKED:

U. S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4} \frac{31}{512}$
 1924

Accessories Found: (Condition and Source) THE REMAINS OF AN ORIGINAL BT.
A 24" FIR, NOW A BADLY DECAYED 36" STUMP WITH NO MARKINGS, BEARS
N 59° E 13 $\frac{1}{2}$ FT., NO TRACE FOUND OF ORIGINAL SE LAUREL BT..

(1924 RETRACEMENT) FOUND: A 12" NOW 16" MAPLE, ALIVE WITH WELL-
HEALED SINGLE BLAZE, BEARS S 39° E 31 $\frac{1}{2}$ FT.,

A 16" D. FIR, NOW BLOWN DOWN, WITH WELL-HEALED SINGLE BLAZE BEARS
N 71° W 33 $\frac{1}{2}$ FT.,

#181 X

G. S. File No. 60/17-9 Page 1 of 1
C

(REN. #126 BT'S): FOUND: AN 11", NOW 13" MAPLE, ALIVE WITH ~~PA~~ SCRIBING "1/4 SICS"

VISIBLE ON PARTIALLY-HEALED DOUBLE BLAZE, BEARS N21°E 34⁵ FT., (REC. N18°E 37⁵ FT.)

AND A 17" D. FIR, NOW AN 18" BLOWDOWN WITH PARTIALLY-HEALED DOUBLE BLAZE BEARS S86°W 23⁰ FT.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 22" D. FIR, SCRIBED "1/4 SICS BT"
ON A DOUBLE BLAZE, BEARS N84°E 29⁷ FT.

Location and Comments: CORNER LOCATED BENEATH 36" FIR WINDFALL.	<u>19° EAST</u>	Compass Declination
	<u>DOUGLAS CO. SURVEYOR'S OFFICE</u>	Agency
	<u>GARY L. LANGRISH</u>	Party Chief
	<u>Gary L. Langrish</u>	Notekeeper
	<u>FRANK C. SILAGY</u>	Witnesses
	<u>TERRIE PLOUFF</u>	

OK
[Signature]