

DATE: 10-5-78

T 29 S R 5 W

22	23
27	26

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s #2 & 1957 RESURVEY

Monument(s) Found: (Condition and Source) A 2 INCH DIAM. IRON

PIPE WITH A U.S. B.L.M. CADASTRAL SURVEY BRASS CAP

ATTACHED MARKED

" T 29 S R 5 W "

S 22	S 23
S 27	S 26

1957

ALSO FOUND 3/4" IRON PIPE PER RENEWAL NUMBER 2

PIPE BEARS N 6° W 37 INCH 3<sup>08</sup> FEET

Accessories Found: (Condition and Source) ORIGINAL BEARING

TREE 1) A W. OAK 12 NOW 24 INCH DIAMETER BEARS

N 6° W 231<sup>5</sup> FEET (REC 231<sup>0</sup> FEET). SINGLE BLAZE

HAS BEEN PREVIOUSLY OPENED TO THE HEART OF THE TREE

TREES PER 1957 RESURVEY: 2) A W. OAK 18 INS.

DIAM. BEARS N 58° E 70<sup>1</sup> FEET TO CENTER OF BASE (REC 69<sup>6</sup> FEET) TREE

HAS WELL HEALED SINGLE BLAZE. 3) A W. OAK 12 NOW 15 INCHES DIAM.

#196 L1

G. S. File No. 6017-12 SHEET Page 1 of 1

C

BEARS S13°W 100 FEET. TREE HAS PARTIALLY HEALED SINGLE BLAZE.

4) A W. OAK 12 1/2 NOW 15 INS. DIAM BEARS S36°W 51 ± FEET TO  
TREE HAS WELL HEALED SINGLE BLAZE  
CENTER OF BASE (REC. S37°W 50 ± FEET) S) A W. OAK IS NOW 18  
INS. DIAM. BEARS N15 1/2°W 140 ± FEET, TREE HAS WELL HEALED SINGLE  
BLAZE.

RENEWAL

Monument Set: (Procedure and Description) NONE  
~~NO~~

New Accessories: (Description) NONE

Location and Comments:	<u>20° EAST</u>	Compass Declination
	<u>DOUG. CO. SURV. OFF.</u>	Agency
	<u>LARRY E. MONREAN</u>	<u>CREW</u> Party Chief
	<u>Jerry E. Monrean</u>	Notekeeper
	<u>P.L. EARLE</u>	Witnesses
	<u>T.R. PLOUFF</u>	
		<u>OK</u> <u>JPL</u>