

T 30 S R 6 W

NE COR
DLC *47

LOCATED IN SECTION 13

DATE: 10-9-78

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 171, 178, 224, & CS FILE 41/193

Monument(s) Found: (Condition and Source) FOUND AS RECORDED

IN RENEWAL NO. 224. BRASS CAP MONUMENT HAS

BEEN BENT OVER AT GROUND LEVEL.

Accessories Found: (Condition and Source) CORNER ACCESSORIES

AS RECORDED IN RENEWAL NO 224 WITH ONE NOTE.

THE CORNER OF THE HOUSE AS REFERRED TO IN

RENEWAL NO. 224 BEARING N38°W 33⁶ FEET

IS NOW THE SOUTH SOUTHEAST CORNER, AS

AN ADDITION IS BEING PLACED ON THE EAST SIDE

OF THE HOUSE.

SHEET

Page 1 of 1

C. S. File No. 60/17-13

225 ✓

e

RENEWAL

Monument Set: (Procedure and Description) AS THE BRASS CAP
MONUMENT HAS BEEN BENT OVER AT GROUND LEVEL WE STRAIGHTEN
BENT PIPE AND RESET AT SAME LOCATION WITH BRASS CAP
3 INCHES ABOVE GROUND. IN ADDITION TO FINDING THE STONE
AND PIPE AS RECORDED IN RENEWAL NO. 224 WHICH WE

New Accessories: (Description) AT PROPER LOCATION
REPLACED (THE STONE BELOW
GROUND THE PIPE ~~REFLUSH~~ FLUSH WITH BRASS CAP), ALSO FOUND WATER
LINE PIPE RUNNING EAST AND WEST WHICH IS ALONG
THE NORTH EDGE OF THE CORNER MONUMENT. WATER
LINE IS APPROXIMATELY $\frac{20}{24}$ INCHES BELOW GROUND SURFACE.

Location and Comments: 20° EAST Compass Declination
DOUG. CO. SURV. OFF. Agency
LARRY E. MONREAN Party Chief
Larry E. Monrean Notekeeper
KAREN REED Witnesses
P.L. EARLE

OK
[Signature]