

T 315 RIW

DATE: 10/19/78

1/1024

SEC 20

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

ORE LIC 222

1972

Previous Renewal #'s M 42-75

Monument(s) Found: (Condition and Source) 3" BRASS CAP

ON A 2" IRON PIPE IN A MOUND OF STONE.

THIS BRASS CAP WAS STAMPED "CSNN 1/256"

IN ERROR. I CHANGE BRASS CAP

TO READ "1/1024".

Accessories Found: (Condition and Source)

A 10" DOUG FIR BEARS S 43° E, 13.4 FT.

I REMOVE "CSNN 1/256" FROM FACE

& SCRIBE "1/1024" IN IT'S PLACE.

A 10" DOUG FIR BEARS N 18° E,

48.7 FT, I REMOVE "CSNN 1/256" FROM

FACE & SCRIBE "1/1024" IN IT'S PLACE.

ALL OTHER SCRIBING ON THESE  
BT'S REMAINS THE SAME.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments: 19° 30' E Compass Declination  
CORRECTIONS MADE DENNIS GAYLORD Agency  
BY DIRECTION OF " " Party Chief  
J. A. HOFFBUHR LORI COLE Notekeeper  
Witnesses  
OK JHL