

T 19-10

DATE: 11/2/78

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) No evidence of 1/4
corner between section 33 and 34, T19S R10W
was found. There are some new blaze trees
going into the area, but could not find
any old blaze.

Accessories Found: (Condition and Source) _____

No evidence of BT's or other accessories found.
The area has a lot of windfall trees. There
are two stumps that have been cut into.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: 20° E Compass Declination

(USFS) Deputy Co. Surveyor Agency

Ernest K. Alvarado Party Chief

" " " Notekeeper

CAROL DICKISON Witnesses

OK
[Signature]