

T19-10

DATE: 11/8/78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s BLM 1952

Monument(s) Found: (Condition and Source)

Brass cap in good condition mkd.:

U. S. GENERAL LAND OFFICE SURVEY

Penalty \$250⁰⁰ for Removal

1/4 S33
S4
 1952

Accessories Found: (Condition and Source)

40" D-Fir, brs. S6°W, dist. 7¹'

43" D-Fir, brs. N75°E, dist. 97'

23 T19-10X

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:

Go to Sec. Corner for (USFS) Deputy Co. Surveyor
32,33,5,4 which is located 6' East of
N. Fork Access Rd.
From there go East
 $\frac{1}{2}$ mile to corner.

20°E

Ernest R. Alvarado

Colin Long

Diane Lawson

Ernest R. Alvarado

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK [Signature]

CSA