

T19-10

DATE: 8 Dec. 1978

Condition Report Only

Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) No evidence of
1/4 CORNER between section 27 AND 28, T19S
RIW WAS FOUND, THE BEARING AND DISTANCE
fell in old clearcut AND THE AREA HAS ALL
slide down to the creek. GLO Notes
CALLS FIT THE AREA.

Accessories Found: (Condition and Source) NO evidence of
BTs or other accessories found.

Page ___ of ___

U. S. File No. 60-17-30

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: 20° E Compass Declination
(USFS) Deputy Co. Surveyor Agency
Ernest R. ALVARADO Party Chief
Ernest R. ALVARADO Notekeeper
CAYOL Dickison Witnesses

OK
JHL