

COUNTY SURVEYOR'S
T263 R1W OFFICE

529	528
532	533

1979

DATE: 8/14/79

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) ORIGINAL CORNER
STONE SET FIRMLY IN PLACE, MEASURES 14" x
10" x 8" - NO MARKS VISIBLE ON STONE.

Accessories Found: (Condition and Source) A 36" DOUG FIR STUMP
BEARS N37°E, 15.84 FT. & HAS A ^{SINGLE} HEALED BLAZE.
A 25" FIR STUMP (HI STUMP) BEARS S59°E, 13.8 FT.
(RECORD S64°E, 13.2 FT.) HAS A SINGLE HEALED
BLAZE. A 36" DOUG FIR STUMP BEARS
S70°W 19.8 FT. HAS A SINGLE HEALED BLAZE.
(RECORD S68°W) 36" WINDFALL IS NOW A

#97 X

STUMP. Root Hole Bears N34'W,
12.5 ft. NO MARKS OR SCARS VISIBLE.

RENEWAL

Monument Set: (Procedure and Description) MOVING CORNER
STONE ASIDE, I SET IN IT'S PLACE A 2 1/2"
BRASS CAP ON A 1" GALV. IRON PIPE. BRASS
CAP IS MARKED AS SHOWN ON REVERSE.
I BURY CORNER STONE ADOUSSIDE PIPE.

New Accessories: (Description) SET A 5/8" IRON
ROD WITH A 1 1/2" ALUM. CAP IN ORIG
SW B.T. STUMP. & MARK CAP "RM"
CAP BEARS S67°30'W, 18.85 ft. A
5/8" IRON ROD WITH A 1 1/2" ALUM CAP,
MARKED "RM" BEARS N33°E, 13.02 ft.

Location and Comments:

20° E

Compass Declination

VIS. F.S.

Agency

THIS CORNER IS 100

DENNIS GAYLORD

Party Chief

FT. SOUTH OF F.S.

" "

Notekeeper

ROAD #2629 IN A

DARREL MYERS

Witnesses

PROPOSED CLEARCUT

(ANY NEW B.T.'S

SET WILL BE CUT)

OK
[Signature]