

DATE: 10/22/79

T235, R4W

$\frac{1}{4}$ $\frac{S6}{S7}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 11, 17, 28, 151

Monument(s) Found: (Condition and Source) A 2" x 1/2" x 12"
and a 3 1/2" x 3/8" x 18" iron bar protruding
6" and 9" respectively from an rough mound
of stone located in an old east-west
fenceline. (see renewal #28)

Accessories Found: (Condition and Source) badly rotted remains
of fir stump at N47°W, 13² ft. originally a 30" fir.
no remains of other original bearing tree. From renewal
#11, 36" fir is now a 40" downed tree, no scribe
marks visible, measures S43°E, 52² ft as per record;
40" fir is now a fir stump, 50" diam. at base 26" DBH
5 ft. tall BT scribe visible in otherwise decayed, mea-
asures N59°E, 33° ft.

#161 X

C. S. File No. 6037 Page 1 of 1

From renewal #17 tree recorded as N63°E 40 1/2 ft is now a 20" fir stamp 16" tall no scribe marks visible but possible blaze scar, record new bearing and mark new tag as N66°E, 25 3/4 ft. From renewal #28 find 18" now 24" R (is D) fir with well healed double blaze, measures S35°E 29 3/4 ft. From renewal #151 find 11" now 14" D fir with partially RENEWAL healed double blaze scribe marks visible, measures N35°E 26 1/4 ft.

Monument Set: (Procedure and Description) Accepting
 position of iron bars (as mention in "monuements found") as supported by evidence noted above, we set 36" x 1" iron pipe with brass cap attached. cap marked DOUGLAS COUNTY SURVEYOR, cap is set in mound of stone 30" x 22" x 12" high. Iron bars set alongside cap.

New Accessories: (Description) T 235
S6
S7
R4W
1979

NEW BT's 9" D. fir marked T235 R4W S 7 CS BT on double blaze S21°W, 41 1/2 ft. 14" D. fir marked T235 R4W S6 CS BT on double blaze N19 1/2°W, 42 1/2 ft.

Location and Comments: 19°E Compass Declination
DCSO Agency
S.J. FLAUSE Party Chief
" Notekeeper
F. SILAGY Witnesses
B. STEWART

OK 