

DATE: 12/6/79

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

B.L.M. brass cap in good condition, mkd.: T19S R9W
S17 | S16
S20 | S21
1969

Accessories Found: (Condition and Source) _____

13" D-Fir, brs. N67°W, dist. 14²⁵', healed face
15" D-Fir, brs. S38°W, dist. 17⁴', healed face
10" D-Fir, brs. S58°E, dist. 18⁹⁵', healed face, surveyor's
washer stamped #239
16" D-Fir, brs. N42°E, dist. 11²⁵', healed face, surveyor's
washer stamped #239.
6" red bands and blazes painted on BT's

Attention signs on fiberglass fence posts placed North
and East of corner.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:

From junction of USFS
rds. #23 & #919, go
East on road #23 approx.
0.4 mile to location
post on left side of the
road. Then go South 295°
to corner.

20° E

(USFS) Deputy Co. Surveyor

Ernest R. Alvarado

Carol Dickison

Colin Long

Ernest R. Alvarado

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]