

DATE: 12/12/79

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) Condition good.

B.L.M. brass cap lies under NE side of larger boulder

in center of creek, mkd.:

1/4
S17 | S16
T19S R9W
1968

Accessories Found: (Condition and Source) _____

26" D-Fir, brs. N22°E, dist. 24⁹', healed face

27" Hemlock, brs. S68°W, dist. 56⁰', scribing visible

6" red bands and blazes painted on BT's

Attention sign on fiberglass fence post placed

approx. 82' North of corner.

Page 1 of 1

C. S. File No. 6037-26

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:	<u>20°E</u>	Compass Declination
From junction of USFS (USFS) Deputy Co. Surveyor		Agency
Rds. #23 & #919, go <u>Ernest R. Anderson</u>		Party Chief
East on rd. #23 approx. <u>Carol Dickison</u>		Notekeeper
0.4 mile to section line		Witnesses
post on left side of road. <u>Colin Long</u>		<u>OK</u>
Location poster is on back of post.		<u>[Signature]</u>
Then go approx. 2768' North along		
posted line to corner. <u>Corner</u>		
lies under NE side of larger boulder		
in center of creek.		