

DATE: 3/18/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s M68-2

?

Monument(s) Found: (Condition and Source) (T20S R10W) E1/16 S-4 -80

5/8" re-bar, 3" above ground

(SW COR
COR, LOT 4 ?)

Accessories Found: (Condition and Source)

26" D-Fir, brs. N45°30' E, dist. 10⁹', partially healed face, see

scribing visible: S3 BT (N47°30' E 11.0')

30" D-Fir, brs. N29°45' W, dist. 51⁹', partially healed face,

scribing visible: S4 BT (N28°30' W 51.6')

+

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

USFS Attention and Boundary signs on metal fence posts
placed West and North of corner.

Location and Comments:	<u>20°E</u>	Compass Declination
Take Burma Rd. to junction	<u>Deputy CoS Surveyor</u>	Agency USFS
of I.P. Rd. #20-10-3.0	<u>Ernest R. Alvares</u>	Party Chief
and F.S. Rd. #2319-038.	<u>Carol Dickison</u>	Notekeeper
Location poster is on bank	<u>Colin Long</u>	Witnesses
West of junction.		
Corner lies N6°E, dist. 500'		
and lies in flat area.		

OK *[Signature]*