

DATE: 3/19/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 1952 BLM SURVEY

Monument(s) Found: (Condition and Source) (T20S R10W)

U.S.G.L.O.S. brass cap in good condition, mkd.: 1/4 S34 T19-10

S3 T20-10

1952

Accessories Found: (Condition and Source) _____

- (16") 27" Hemlock, brs. N72°E, dist. 23⁸' OK
- (60") 70" Cedar, brs. S76°30'W, dist. 47⁶', scribing visible (S78° 462')

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Attention sign and boundary sign placed on metal fence post
west of corner.

Location and Comments: 20°E
Take Burma Rd. to I.P. Rd. Deputy Co. Surveyor
#20-10-3.1. Location Ernesto R. Alvarado
poster is on stump on Ernesto R. Alvarado
North side of road, approx. Greg Martin
0.4 mile from junction
w/rd. #20-10-3.0. Corner _____
lies NE, approx. 300' from poster,
in open area below road.

Compass Declination
Agency USFS
Party Chief
Notekeeper
Witnesses

OK