

DATE: 3/24/80

T195
East WC for $\frac{1}{4}$ $\frac{S14}{S23}$
R9W

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1958 Resurvey

Monument(s) Found: (Condition and Source) BLM Brass cap
on 2" iron pipe firmly set and protruding from ground
0.5 ft. Cap is marked U.S. Cadastral Survey

T195 R9W

WP

$\frac{S14}{S23}$

1958

Bureau of Land Management

Accessories Found: (Condition and Source) An 12" now a 16" D Fir
bears N11°E, 5.9 ft (record N10°E, 5.9 ft.) there is a blazed
"X" on the south face of tree and a healed blaze at base of
tree no scribing visible. An 8" fir now an 8" by 15 ft.
tall dead snag bears S64°W, 7.5 ft. (record S68°W, 7.9 ft.)
open blaze at base of snag scribed "BT."

#13X

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) An 11" D. fir bears $544^{\circ}E$
on a double blaze
16 $\frac{1}{2}$ ft., scribed "T195 R9W WC S23 CS BT" A 14" D. fir bears
 $506^{\circ}E$, 24 $^{\circ}$ ft., scribed "WC T195 R9W S23 CS BT" on a double
blaze. An 8" D. fir bears $N20^{\circ}W$, 12 $^{\circ}$ ft., scribed "WC T195
R9W S14 CS BT" on a double blaze. We tag all new trees
with DCSO tags.

Location and Comments: 19 $^{\circ}E$ Compass Declination
DCSO Agency
Deputy Stephen Flano Party Chief
SJF Notekeeper
SHAWN MEANS Witnesses
TERRY (TP) PLOUFF

OK
[Signature]