

DATE: 3/27/80

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s #2 T19-10 ; #2 T19-9

Monument(s) Found: (Condition and Source) _____

Douglas Co. brass cap, mkd.:

T19S

S25 |

R10W

S36 |

R9W

1964

Accessories Found: (Condition and Source) _____

(40") 42" D-Fir, brs. N37°W, 40', healed blaze (N 3 1/2° W 4.0')

(38") 41" Hemlock, brs. S83°W, 473', scribing visible (46.9')

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

BT's painted w/red 6" bands and blazes

Area flagged w/pink "Land Line ribbon

Location and Comments:

20°E

Compass Declination

Go up USFS Rd. #23 about
5.0 miles to location
poster on North side of
road, then go North
10 ch. to cor. Cap
lies on North face at
base of Fir.

Deputy CoS. Surveyor

Ernest R. Alvarado

Colin Long

Carol Dickison

Agency U.S.F.S.

Party Chief

Notekeeper

Witnesses

OK [Signature]