

DATE: 3/28/80

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s M43-22

Monument(s) Found: (Condition and Source) (T19S R10W)

Brass cap mkd.: W1/16 S25

S36

1971

4185

Accessories Found: (Condition and Source)

(36") 39" Fir, brs. Due North, dist. 22⁰', healed face (20.4)

(20") 23" Hemlock stump, 6' high, brs. S17⁰E, dist. 15¹' (14.27)

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

6" Bands and blazes painted on BT's

Area flagged w/pink "Land Line" ribbon

Location and Comments:

20°E

Compass Declination

Go to Sec. Cor. location poster, which lies 0.2 mile up F.S. Rd. #943.

Deputy Co. Surveyor

Agency USFS

Ernest R. Alvares

Party Chief

Colin Long

Notekeeper

Follow tree line approx.

Carol Dickison

Witnesses

800' North to Sec. Cor.

Then go East 1100' to W 1/16 Cor.,

which lies on SE slope 100' from East

side of top of spur on tree line. Also, corner lies N9°W,

approx. 700' from West end of 6th bridge over N. Fork on

USFS Rd. #23 (approx. 4.2 miles up)

OK