

DATE: 3/28/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s #14

Monument(s) Found: (Condition and Source)

Brass cap mkd.:	TL9S R10W
	S26 S25
	S35 S36
	1971
	4185

Accessories Found: (Condition and Source)

- 20" 28" Fir, brs. N6°E, dist. 31⁰' (30.7)
- 32" 39" Fir, brs. N13°W, dist. 32⁸' (33.1)
- 22" 22" Fir, brs. S50°W, 54⁸' dist. (59.8)
- 24" 33" Fir stump, brs. S68°E, dist. 21⁵' (21.0)

-All BT's have healed faces

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

BT's painted w/red 6" bands and blazes

Area flagged w/pink "Land Line" ribbon

Location and Comments:

Go up USFS Rd. #943 approx. 0.2 mile to location poster on Alder North of road (at tree line). Corner lies North approx. 800' in corner of unit on NW slope.

20°E

Deputy USFS Surveyor

Ernesto R. Alvarez

Colin Long

Carol Dickison

Compass Declination

Agency - USFS

Party Chief

Notekeeper

Witnesses

[Handwritten signature]