

T 323 RSW

DATE: 5/23/80

1/4 $\frac{S 22}{S 27}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 87

Monument(s) Found: (Condition and Source) 1/4" iron pipe firmly set
and protruding 0.2 ft from ground from renewal #87. Pipe is approx.
1 ft. west of a random East-West fence line running East only
from 1/4 corner.

Accessories Found: (Condition and Source) Search for but find
no evidence of original bearing trees. From renewal #87
two bearing trees are found; An 8" now an 18" D. Fir bears
S 51° W, 18[±] ft (as per record) has healed single blaze
no scribing visible and is tagged with a BLM bearing tree tag,
; And a 10" now a 20" Madrone bears N 52° E, 28[±] ft. (record
N 52° 25' E. 29[±] ft) has partially healed single blaze with scribe

207X

marks visible and is tagged with a BLM bearing tree tag (which is marked S 52° W, 28 ft.)

RENEWAL

Monument Set: (Procedure and Description) Because of
no connection in record to original evidence we
do not set a brass cap but only perpetuate the
position of 1/4 corner as determined by Wenderath in 1956
CS File 42/88. Iron pipe is still firmly set we do not disturb
but add a bearing tree as follows.

New Accessories: (Description) A 5" Madrone bears N 0° E,
14° ft., bark scribed "1/4 S22 CS BT."

No suitable trees available in other quadrants

Location and Comments: 19° E Compass Declination
DCSO Agency
Deputy Stephen John Flouse Party Chief
Deputy John Flouse Notekeeper
TERRIE PLOUFF Witnesses

OK 