

DATE: 5/27/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 35

Monument(s) Found: (Condition and Source) _____

Corner is a 60" Spruce stump. A County brass cap lies

6" North and is marked:

S20S		
S20	S21	R
S24	S28	11
1964		W

Accessories Found: (Condition and Source) _____

52" Fir stump, brs. N52°E, 118.0', scribing visible

Hemlock is missing - fell in slide area

Found probable Spruce B.T., brs. S25°W, dist. 22.9' (now broken log. Several pieces are on top of root wad)

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Attention sign on metal fence post placed near corner

B.T.'s painted with red blazes and 6" bands

Area flagged with pink "Land Line" ribbon

Note: Distances are to side and center of trees at root crown.

Location and Comments:	20°E	Compass Declination
Go 0.3 miles past Rd. #4811 052 to spur rd. on North side, Stay East at first junction. Poster on switchback. Corner lies S70°W, approx. 1200' (25') on South side of creek) also lies S10°W of landing	Douglas Co. Deputy Surveyor <i>Crest B. Alvarez</i> Colin Long Chris Ebert, NRA YACC	Agency USFS Party Chief Notekeeper Witnesses

OK/ful