

DATE: 5/27/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 34

Monument(s) Found: (Condition and Source) _____

County brass cap in good condition, 3" above ground, mkd.:

T20S

S29 | S28

S32 | S33

R11W

1964

Accessories Found: (Condition and Source) _____

32" Rotten Spruce stump (Orig. BT), brs. N60°E, dist. 41.8'
(40.4' to face)

8" down D-Fir, rootwad brs. N16°E, dist. 12.5', open face,
scribing visible

11" D-Fir, brs. N14°W, dist. 11.0', healed face

20" D-Fir, brs. S9°W, dist. 18.7', healed face

53" D-Fir stump, (Orig. B.T.), brs. S46°E, dist. 8.1' (6.0' to
face)

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Attention sign on metal fence post placed near corner

B.T.'s painted with red blazes and 6" bands

Area flagged with pink "Land Line" ribbon

Note: Distances are to side and center of trees at root crown.

Location and Comments: _____ 20°E _____ Compass Declination
From junction of USFS Douglas Co. Deputy Surveyor Agency USFS
Rd. #4811 and #053, go Cement P. Edwards Party Chief
along Rd. #053 approx. Carol Dickison Notekeeper
0.6 mile to where spur _____ Survey Tech
#056 goes off to left. _____ Witnesses
Location poster is on _____
stump to left of road. Bob Walters, NRA YACC
From location poster, _____
corner lies West approx. 1900' in stand of small
timber West of flat timber area, on gentle slope.

OK ghal