

DATE: 5/28/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #37

Monument(s) Found: (Condition and Source) \_\_\_\_\_

Co. brass cap is out of ground. (Lathe marks spot for brass

cap.) Cap is mkd.: T20S

S I S

21 | 22

R11W

1964



Accessories Found: (Condition and Source) \_\_\_\_\_

12" Hemlock snag, 20' high, brs. S16°W, dist. 47.3', scribing visible

14" Hemlock stump, 1½" high, brs. S85°E, 76.2'

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

Attention sign on metal fence post placed near corner  
B.T.'s painted with red blazes and 6" bands  
Area flagged with pink "Land Line" ribbon

Note: Distances are to side and center of trees at root crown.

Location and Comments:	20°E	Compass Declination
Go up USFS Rd. #4811 to spur road opposite #046.	Douglas Co. Deputy Survey	Agency USFS
Travel Spur 0.4 mile to location poster West of road. Corner lies approx. N64°E, 700'. Both B.T.'s are on ridge top. Corner is on steep North slope.	<u>Ernest R. Alvarado</u> <u>Colin Long</u> <u>Chris Ebert, NRA YACC</u> <u>Brien Gonzalez, " "</u>	Party Chief Notekeeper Witnesses

OK  
*[Signature]*