

DATE: Sept 10, 1980

T315 R5W

$\frac{1}{16}$   
S4 | S3

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s none

Monument(s) Found: (Condition and Source) A 2 1/2" x 28" iron pipe  
with a brass cap loosely set and protruding 19" from ground,  
monument leans 10" off of perpendicular to the NW.

Cap is marked as follows:

"U.S. DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT"

S 1/16

S4 | S3

1966

Accessories Found: (Condition and Source) A 31" DBH D. Fir bears  
(record S52°E, 29°FT)  
S 50°E, 29± ft distant; tree has well healed single blaze  
with no scribing visible and is tagged with 2 BLM, BT tags.

The original 35" D. Fir has been removed during  
road work.

#115 X

U.S. File No. 6111-15

Page 1 of 1

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

We dig to base of monument and find its measurement to the original Southeast bearing tree is 29<sup>2</sup> ft (as per record) bearing remains S 50° E. We plumb monument firm soil about its' base and add a rough pile of stone around monument measuring 16x18x10" high. Brass cap is level with top of pile of stone.

New Accessories: (Description) A 8" D fir bears N 48° E, 35<sup>8</sup> ft; tree is scribed "S 1/16 S3 CS BT" on a double blaze. A 13" D. fir bears S 22° W, 44<sup>2</sup> ft.; tree is scribed "S 1/16 S4 CS BT" on a double blaze. A 12" D fir bears N 53 1/2° W 50.<sup>00</sup> ft.; tree is scribed "S 1/16 S4 CS BT" on a double blaze

Location and Comments:

\_\_\_\_\_ 19° E \_\_\_\_\_ Compass Declination  
\_\_\_\_\_ DC 50 \_\_\_\_\_ Agency  
Deputy Stephen John Flaws \_\_\_\_\_ Party Chief  
~~Stephen John Flaws~~ \_\_\_\_\_ Notekeeper  
\_\_\_\_\_ BILL STEWART \_\_\_\_\_ Witnesses  
\_\_\_\_\_ KAREN MOSELY \_\_\_\_\_