

DATE: 9.29.80

T295 R3W

S10 ↑

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s BLM Resurvey 1964

Monument(s) Found: (Condition and Source) A BLM Brass Cap on a 2" iron pipe protruding 7" from ground and is firmly set. Cap is marked "US BUREAU OF LAND MANAGEMENT"

T295 R3W
S3	S2
 S10 | S11
 1964

Accessories Found: (Condition and Source) A thorough search of the area employing original line calls yields no evidence of original trees.

From the BLM resurvey the following trees are found. A 10" now a 15" DBH, D. Fir bears N 28 1/2° E, 110.9 ft (as per record); tree has healed single blaze with no scribing visible. A 10" now a 16" DBH, D. Fir bears

#135 X

S 50° E, 30° ft (record S 40° E, 30° ft); tree has
 healed single blaze no scribing visible. A 7" now a
 9" D.B.H., D. fir bears S 51 1/4° W, 6° ft (record S 51 1/4° W,
 5° ft); tree has healed single blaze no scribing visible.
 A 10" now a 12" D.B.H., D. fir bears N 47 3/4° W, 67° ft (record
 N 47 3/4° W 68° ft); tree has healed single blaze no scribing
 visible. RENEWAL

Monument Set: (Procedure and Description) We accept
position of monument as there is no evidence
that it has been disturbed. Discrepancies
from record bearings and distances seem to
indicate recording or measurement errors.

New Accessories: (Description) A rough fence corner
with fences running North and East lies
approximately 20 ft north of the brass cap.
All trees are retagged with DCSO bearing
tree tags.

Location and Comments: 19° E Compass Declination
DCSO Agency
 Deputy Stephen John Flanso Party Chief
Stephen John Flanso Notekeeper
Bill STEWART Witnesses

[Handwritten signature]