

T245 R4W

527

N.E.

DLC

44

DATE: 12/12/80

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 130

Monument(s) Found: (Condition and Source) 1" iron pipe protruding 10" from ground. Pipe is leaning slightly northwest. Bearings and distances to accessories found (as mentioned below) are taken from the point where pipe enters ground. After checking accessories the pipe location is referenced out and the pipe is removed so it might be replaced by a DCSO brass cap monument, however 2" under the ground surface at the position referenced out for the iron pipe a 2 1/2" brass cap on a 1" iron pipe is found. "COUNT SURVEYORS OFFICE" The cap and pipe monument is firmly set and marked

Accessories Found: (Condition and Source)

T245 R4W

N.E.

DLC

44

1963

An original 12" oak now a dead 26" DBH White oak bears S 54 1/4° E, 291 1/2 Ft dist. (original record S 54 1/4° E, 492 lbs.; dist in renewal #130 is recorded as 291 1/2 Ft. or 442 lbs.) because of this discrepancy and the indistinct nature of the visible scribe marks the tree is opened further and near the original 12" diameter a lower blaze is found with the clearly marked scribing "BT." #158 X

An original 30" oak now a 54" ^{DBH} Black oak bears, $55\frac{1}{2}^{\circ}E$
369 ⁶ ft. dist. (as per original record) because renewal #130
is not conclusive regarding the markings on this tree the tree
is opened further and near the original diameter a lower
blaze is found with the clearly marked scribing "BT". Both
these trees are tagged with 1963 NCSO bearing tree tags.

RENEWAL

Monument Set: (Procedure and Description) The position of the
found monuments is accepted and the discrepancy
with the original record is assumed to result from an error
in the original written record where a distance of 442 lks. to

the 12" oak is recorded as 492 lks. Some soil is excavated from
around the found brass cap and it now protrudes 4 inches from the soil
Found continued: cont'd below at Loc. and Comm.

New Accessories: (Description) From renewal #130 a 12"

W. oak now a 16" W. oak bears $N 15\frac{1}{2}^{\circ}E$, 903 ft. (as per
record), tree has healed single blaze with no scribing visible,

And a 7" W. oak now a 13" W. oak bears $N 69^{\circ}W$, 697 ft.
(as per record), tree has healed single blaze with no scribing
visible. New NCSO bearing tree tags are added to these two trees,

Location and Comments:

the 1 inch iron pipe is
replaced at the south
edge of the brass cap
and now protrudes
12 inches from the ground.

<u>19°E</u>	Compass Declination
<u>NCSO</u>	Agency
<u>Deputy Stephen John Flouse</u>	Party Chief
<u>Stephen John Flouse</u>	Notekeeper
<u>Colleen O'Keefe</u>	Witnesses

