

DATE: Feb 5, 1981

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

T315

S18 | S17  
S19 | S20

R5W

Previous Renewal #'s 26, 90, BLM Resurvey

Monument(s) Found: (Condition and Source) From 1966 BLM

resurvey a BLM brass cap on a 2 1/2" iron pipe  
firmly set and protruding 10" above ground.

Cap is marked as follows "US DEPT OF THE INTERIOR"

T315 R5W

S18 | S17

S19 | S20

1966

BUR. OF LAND MANAGEMENT

Accessories Found: (Condition and Source) An original 14 inch diam

now a 36 inch D.B.H., D. fir bears N18°E, 21 1/2 ft. (33 lks)

distant (as per record); this tree has evidence of

an opened and now rehealed blaze and is bark

scribed RS 442 S17 BT. A search is made

for the other original bearing trees, none are

found. From renewal #26 a 7" now a 12 inch D.B.H.

#116 X

C.S. File No. 61/19-4 Page      of   e

W. fir bears S 72° E (as per record), 12<sup>±</sup> ft distant (record 13<sup>±</sup> ft); tree has healed single blaze and bark scribing RS 442. No evidence of 9" W fir is found.

A 12" now an 18 inch D.B.H. W. fir bears N 40° W, 6<sup>±</sup> ft distant (as per record); tree has fully healed

Accessories Cont'd <sup>RENEWAL</sup> (442 is registration number of land surveyor V.S. King. This surveyor did renewal #26)  
Monument Set: (Procedure and Description) single blaze, bark

scribing RS 442 is visible. From renewal #90 a 14" now an 18 inch D.B.H., W fir bears S 86° W (as per record) 37<sup>±</sup> ft distant (record 37<sup>±</sup> ft); tree has partially

healed upper blaze and a fully healed lower blaze the upper blaze is opened and found to read as recorded in 1966 BLM notes, notes in renewal

New Accessories: (Description) #90 record both bearing tree scribings incorrectly as reading "1/4 S" " And an 8" now a 10 inch D.B.H., W. fir bears N 51° E (as per record), 40<sup>±</sup> ft distant (record 41<sup>±</sup> ft.); tree has a well healed double blaze.

Monument location is accepted and all bearing trees are tagged with DCSO BT tags. Tags are marked with bearings and distances

Location and Comments: \_\_\_\_\_ 19° E \_\_\_\_\_ Compass Declination  
\_\_\_\_\_ DCSO \_\_\_\_\_ Agency measured in this renewal.  
DEPUTY LARRY ED MONREAN Party Chief  
Stephen John Flouse Notekeeper  
" " " Witnesses

OK [Signature]