

DATE: Feb 26, 1981

Condition Report Only

Not Found

✓ Renewed

Unrecorded

Surveyed In

Referenced Out

T305 RIW

WC

1/4 56/55

Previous Renewal #'s 31, 194

Monument(s) Found: (Condition and Source) From 1905 resurvey a red fir, 30 ins. diam. marked as the corner tree is now a 34 inch diameter approx 4 foot tall rotted fir stump; an open and burned blaze on its west face has the scribing 4 56 visible, the east face is burned and has a blaze but no scribing is visible. From renewal #31 a 2 1/2 inch brass cap on a 1 inch iron pipe protrudes 15 inches above ground and bears North, 2° feet distant from above corner tree. Cap is marked as follows

COUNTY SURVEYOR

T305 RIW

1/4

6/5

Accessories Found: (Condition and Source) 1968

No accessories from original 1857 survey are found these were destroyed in 1905 resurvey. From 1905 resurvey a white fir, 18 ins. diam. now an 18 inch diameter rotted fir stump bears N 80° W, 15 1/2 feet distant from 1905 corner tree (as per record). No evidence of other 1905

Xbearing tree is found. From renewal # 31 two bearing trees

#3 The above 18 inch diam. fir stump has a single blaze with the scribing 1/4 56 BT visible.

are found; bearings and distances are checked from the brass cap monument. An 11" W. fir now a 15 inch d.b.h. White fir bears $S84^{\circ}E$, 45^{\pm} feet distant (record $S89^{\circ}E$, 46^{\pm} ft) tree has partially healed ^{double} blaze with the scribing S5CS

cont'd p 2

RENEWAL

Monument Set: (Procedure and Description) see pg 2

New Accessories: (Description) see pg 2

Location and Comments: _____

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

DATE: Feb 26, 1981

contd T 305 RIW
WC
1/4 S6 | S5

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

Accessories Found: (Condition and Source) cont'd from pg 1

visible. An 8" W fir now a 12 inch dbh. W. fir bears S56°E
32⁶ feet distant (record S61°E, 32⁶ ft); tree has a partially
healed double blaze with some illegible scribing visible.

Variation of bearing and distance from record in the
preceding two bearing trees probably resulted from an
improperly declinated compass and an improperly reduced

slope distance. And a bearing tree from renewal #194 is found and checked from the brass cap monument. A 6" Douglas Fir now a 6 inch d.b.h., D. Fir bears S 32°W, 22 1/2 feet distant (record S 32°W, 21 1/2 ft) tree has a double blaze with the scribing 1/4 S 6 BT visible.

RENEWAL

Monument Set: (Procedure and Description) Monument location is accepted. The following markings are added to the brass cap monument WC
The arrow in the above markings ↓
points south to the corner tree.

New Accessories: (Description) All accessories are tagged with new DCSO bearing tree tags.

Location and Comments: 19°E Compass Declination
DCSO Agency
Deputy Stephen John Flaus Party Chief
Stephen John Flaus Notekeeper
TERRIE PLUMFF Witnesses
KAREN MOSELY