

DATE: April 6, 1981

T 325
529 | 528
532 | 533
R6W

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 27

Monument(s) Found: (Condition and Source) From renewal #27

a cedar post approx. 12 inches in diameter and 8 feet long (size not recorded previously). Post has rotted off approx. 2 inches below ground level.

The upper 5 feet of said post has fence wires attached from fences running South and East; this section of post has rolled downhill and lies 6 feet southeast of the above mentioned post remains still in ground.

Accessories Found: (Condition and Source) An original Fir, 5 ins

diam., now a 22 inch D.B.H., D. Fir bears S56°E, 28 ⁴/₁₀ feet distant (as per record); tree has an opened face but no scribe marks are observed therein.

tree is opened further to reveal original axe marks and a scribed T (age is verified by a growth ring count.) Possible but inconclusive

#161 X

G.S. File No. 61/19-29

Page 1 of 2

evidence of a stump hole is found at the record bearing and distance of the original north west bearing tree. No evidence of the other original bearing trees is found.

RENEWAL

Monument Set: (Procedure and Description) The location of the cedar post remains in the ground (see monuments found) which agrees with the record bearing and distance from the original southeast bearing tree is referenced out, the post remains are removed, and a DCSO 2 1/2 inch brass cap on a 1 inch x 30 inch iron pipe is placed in the referenced

New Accessories: (~~Description~~) location. The brass cap monument is firmly set and protrudes 5 inches from the ground the cap is marked as follows:

DOUGLAS COUNTY SURVEYOR

T 32 S

S 29 | S 28

S 32 | S 33

R 6 W
1981

(cont'd)

Location and Comments:

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

DATE: April 6, 1981

T 325
S29 | S28
S32 | S33
RGW

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) (cont'd. over →)

Accessories Found: (Condition and Source) _____

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) A 10 inch D.B.H., P. fir
bears N 51 1/2 °E, 26° feet distant, tree is scribed
T32S R6W S28 CS BT on a double blaze. A 6 inch D.B.H., W. fir
bears S 32°W, 29.6 feet distant, tree is scribed T32 S R6W
S 32 CS BT on a double blaze. An 11 inch D.B.H., D. fir bears
N 03°W, 28.6 feet distant, tree is scribed T32 S R6W S29 CS BT
on a double blaze. All bearing trees are tagged with DCSO, BT tags.
Location and Comments: _____

19°E Compass Declination

DCSO Agency

Deputy Stephen John Flause Party Chief

Stephen John Flause Notekeeper

TERRIE PLOUFFE Witnesses

KAREN MOSELY

OK
[Signature]